

MANUEL D'UTILISATION – Réf. 6030

Fonctions

Pile : 1 x 1.5V (LR44)

Date/heure/alarme

Horloge avec sonnerie et fonction alarme

Plage de température : -10+70°C ou +14+158°F


Plage hygrométrie : 10 à 90 %

Résolution : 0,1°C, 1 %

Précision : +/-1°C, +/-5 %


Enregistrement des températures mini et maxi

Thermomètre




Face

1. Ecran
2. Heure
3. Température
4. Zone de confort
5. Boutons
6. Support
7. Humidité
8. Trou de suspension
9. Couvercle pile




Dos



Côte

Mise en marche

Installer la pile



Heure : AM 12:00

Date : 1 M 1 D


Alarme : AM 12:00, alarme OFF

Température et humidité actuelle


Référence produit : 6030
Type de batterie: 1X1.5V 160mAh LR44 Alkaline Cell
Adresse du fabricant de pile:
SHENZHEN WEINENG ELECTRONICS CO.,LTD
7th floor of A-building, Senyang High-tech Park,
Tianliao community, Guangming District,
Shenzhen.China
Site web : www.weineng-gd.com
Email:weinengdz@163.com




Programmation date et heure



Programmation alarme



Activation Alarme/sonnerie par heure



Le son de l'alarme sonne bi bi bi pendant 1 min. La sonnerie horaire sonne bi-bi une fois

Température max/min et humidité : enregistrement et remise à zéro

Appuyer sur max/min pour avoir les minima et maxima de température et humidité. Appuyer 3 secondes pour remettre à 0.

Zone de confort

Température : entre 20 et 26°C (68 et 78°F) / humidité : entre 50 et 70% (humide >70 %, sec <50%). Inconfort température : <20°C (68°F) ou >26°C (78°F)



USER MANUAL – Ref. 6030

Functions

Battery: 1.5 Vx1 (LR44)

Time/date/alarm

Clock with hourly chime and alarm function

Temperature range: -10+70°C or +14+158°F


Humidity range: 10-90%

Resolution: 0,1°C, 1%

Accuracy: +/-1°C, +/-5%

Max/Min temperature and humidity records

Thermometer




1. LCD
2. Time
3. Temperature
4. Comfortable level
5. Buttons
6. Support
7. Humidity
8. Hanger
9. Battery cover

Buttons:

MODE: to switch time and alarm mode, hold the button to set time and alarm
 ADJ: to switch time and date mode, in setting mode press and hold the button to increase the value
 MAX/MIN: display the max and min temperature and humidity value. Hold for a long time to reset the memory
 °C/F: to switch the unit of temperature between °C/°F

Use

Open the battery cover; insert the battery, the LCD displays



Time: AM 12:00

Date : 1 M 1 D





Alarm : AM 12:00, alarm OFF

The current temperature and humidity

Product reference: 6030
 Battery type: 1X1.5V 160mAh LR44 Alkaline Cell
 Battery Manufacturer Address:
 SHENZHEN WEINENG ELECTRONICS CO.,LTD
 7th floor of A-building, Senyang High-tech Park,
 Tianliao community, Guangming District,
 Shenzhen,China
 Website: www.weineng-gd.com
 Email:weinengdz@163.com



Programmation date et heure



Alarm sound: bi bi bi bi for 1 minute

Hourly chime sound: bi bi for 1 time

Maximum and minimum temperature and humidity record and clear

Press MAX/MIN button to have the min and max temperature and humidity. Press 3 seconds to clear

Comfort level

Temperature: between 20 and 26°C (68 and 78°F) / humidity: between 50 and 70% (wet >70%, dry <50%)

No comfort: <20°C (68°F) or >26°C (78°F)

